KSTRONG®
UNRIVALED SAFETY.


# HARNESS & LANYARD WASHING INSTRUCTIONS



- This PPE must be washed by Hand
- Using a Mild soap & warm water (less than 40 C)
- DO NOT use solvents or Bleach

**Proper washing keeps PPE safe and increases Durability.**

## HOW TO WASH A HARNESS AND LANYARD




### Remove loose debris
Wipe away surface dirt, mud, or grit using a dry or slightly damp cloth.




### Prepare the cleaning solution
Mix warm water (less than 40 C) with a mild dish soap or gentle detergent in a bucket.



### Scrub gently
Use a non-abrasive sponge or soft cloth moistened with soapy water to work up a lather across the webbing, straps, & stitching. Clean shock-absorbing packs & lanyards similarly without submerging or saturating internal cores.



### Wipe hardware
Clean metal components like D-rings, buckles, snap hooks, and adjusters with a damp soapy cloth.



### Rinse thoroughly
Wipe down all webbing and hardware with a clean sponge dampened only with plain water to remove all soap residue. Avoid soaking the harness or lanyard.



### Blot excess moisture
Press or blot the gear with a clean, dry, lint-free towel.

## HOW TO DRY A HARNESS AND LANYARD



### Hang freely
Hang the harness and lanyard in a well-ventilated, shaded area. Ensure the webbing hangs straight without folds, kinks, or twists.



### Dry metal hardware
Wipe down metal adjusters and hooks with a dry cloth to prevent water spots or corrosion.



### Avoid heat sources
Never use a mechanical tumble dryer, hair dryer, direct sunlight, or industrial heaters. Excessive heat can weaken synthetic fibers and compromise safety rating integrity.

## DO NOT USE



Washing Machines



High Pressure washers



Scrapers or tools

We value your safety and investment in KStrong products, for more info contact customercare@kstrongasia.com