

## PROOF LOADING CABLE TERMINATION ATTACHMENT

ALD-CT

- Proof Load Cable Termination by connecting the proof loading attachment (Dynamometer + cable grip) to the tensioning base unit (ALD-BU) using a hex key .
- **Note** : No need to remove the bending attachment.(ALD-TB)

### Features

- Quick and effortless proof loading
- Digital reading
- Maintenance-free due to the mechanical gear train

### Material

Alloy steel

### Finish

Powder Coating

### Accessories

- 2 No Tensioning Cable ( 1 no spare)
- Break resistant and water proof Hard Case: ALD-CC(S)

